

MAZDA RECALLS

View your vehicles details below

Model: RX8B 6 SPEED MANUAL WITH LEATHER PACK & SUNROOF VIN: JM0FE103100105109 Year: 2007



YOUR VEHICLE IS AFFECTED BY 2 RECALLS

2 Active Recalls 0 Pending Recalls

Result returned on: 25/10/2025 06:52 am AEST

RX-8 (FE) FUEL PUMP DISCHARGE PIPE CRACK RECALL

STATUS RECALL CODE PRA NUMBER

Active R201808 2016/15789 REC-000877

Summary

The fuel pump discharge pipe may have insufficient durability. The effects of fuel pressure and engine/exhaust heat may cause the pipe to deteriorate.

Risk

If the vehicle continues to be used in this condition, continued deterioration may lead to a crack in the pipe and cause a fuel leak, creating an increased risk of fire.

Remedy

Mazda Australia will contact all affected customers by mail. Customers will be advised to present their vehicle to their preferred Mazda Dealer for the replacement of the fuel pump retainer rings and the fuel filter body and installation of thermal insulation pads onto the fuel tank at no charge.

RX-8 (FE) FUEL PUMP AND RETAINING RINGS RECALL

STATUS RECALL CODE PRA NUMBER

Active R201807 2016/15789 REC-000876

Summary

The plastic fuel pump retaining rings on the fuel tank may be exposed to heat from the engine and exhaust due to insufficient thermal insulation, causing heat deterioration of the plastic material of the pump retaining rings. In addition, a reaction force from the gasket (seal rubber) may be applied to the fuel pump rings.

Risk

If the vehicle continues to be used in this condition, continued deterioration may lead to a crack in the fuel pump rings and cause a fuel leak, creating an increased risk of fire.

Remedy

Mazda Australia will contact all affected customers by mail. Customers will be advised to present their vehicle to their preferred Mazda Dealer for the replacement of the fuel pump retainer rings and the fuel filter body and installation of thermal insulation pads onto the fuel tank at no charge.

TAKATA - DRIVER AIR BAG RECALL



 DATE COMPLETED
 RECALL CODE
 PRA NUMBER

 23/01/2018
 R201602
 2015/14761

Summary

In the affected vehicles continued exposure of the driver-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

Remedy

Mazda Australia will contact all affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the driver-side airbag inflator at no charge.

TAKATA - PASSENGER AIR BAG RECALL



DATE COMPLETED RECALL CODE PRA NUMBER 23/01/2018R201702

2015/14761

Summary

In the affected vehicles, continued exposure of the passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

Remedy

Mazda Australia will contact affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the passenger side airbag inflator at no charge.