



# MAZDA RECALLS

View your vehicles details below

Model: RX8C 6 SPEED MANUAL GT VIN: JM0FE103290300659 Year: 2008



## NO OUTSTANDING RECALLS

0 Active Recalls | 0 Pending Recalls

Result returned on: 25/05/2026 02:29 am AEST

### TAKATA - PASSENGER AIR BAG RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED

24/09/2017

RECALL CODE

R201702

PRA NUMBER

2016/15521

#### Summary

In the affected vehicles, continued exposure of the passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

#### Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

#### Remedy

Mazda Australia will contact affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the passenger side airbag inflator at no charge.

### MAZDA6 GG (MPS), RX8 (FE1032) FUEL PUMP RETAINING RING

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED

16/10/2022

RECALL CODE

R202103

PRA NUMBER

REC-004967

**Summary**

Mazda6 GG (MPS) A possibility exists that the fuel pump retaining rings located on the fuel tank, may have been installed incorrectly. RX-8 (FE1032) A possibility exists that the fuel pump retaining rings located on the fuel tank, may have been incorrectly installed and have insufficient durability. The effects of fuel tank pressure and exhaust heat may cause the retaining rings to deteriorate.

**Risk**

On the affected vehicles, the fuel pump retaining rings may crack and cause a subsequent fuel leak, creating an increased risk of fire.

**Remedy**

Mazda6 GG (MPS) Replace the fuel pump retaining rings with modified ones, tightening to the correct torque. RX-8 Replace the thermal insulation pads onto the fuel tank.

---