



# MAZDA RECALLS

View your vehicles details below

Model: B30N DUAL CAB PICK-UP 5A SDX 4X4 VIN: MM0UNY0E400887374 Year: 2010



## NO OUTSTANDING RECALLS

0 Active Recalls | 0 Pending Recalls

Result returned on: 16/06/2026 12:02 pm AEST

### TAKATA - DRIVER AIR BAG RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED

17/09/2017

RECALL CODE

R201602

PRA NUMBER

2015/14761

#### Summary

In the affected vehicles continued exposure of the driver-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

#### Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

#### Remedy

Mazda Australia will contact all affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the driver-side airbag inflator at no charge.

### TAKATA - PASSENGER AIR BAG RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED

17/09/2017

RECALL CODE

R201703

PRA NUMBER

2015/14761 REC-003802

**Summary**

In the affected vehicles, continued exposure of the passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

**Risk**

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

**Remedy**

Mazda Australia will contact affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the passenger-side airbag inflator at no charge.

---