



MAZDA RECALLS

View your vehicles details below

Model: 323 PROTE 5M 1.6 SHADES

VIN: JM0BA116300237370

Year: 1998



NO OUTSTANDING RECALLS

0 Active Recalls

0 Pending Recalls

Result returned on: 24/05/2025 03:27 PM AEST

IGNITION SWITCH RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED

15/02/2017

RECALL CODE

R201605

PRA NUMBER

2015/14997 REC-000867

Summary

An excessive amount of grease may have been applied to the electrical contacts inside the ignition switch. The grease may carbonise due to a heat from the electric arc generated during switch operation. The carbonised grease may accumulate between the electrical contacts (moving contact and fixed contact), reducing the electrical insulation performance inside the switch.

Risk

If the vehicle continues to be used in this condition, the path between the electrical contacts may become conductive, causing heat generation and potentially resulting in smoke and in the worst case, a fire.

Remedy

Mazda Australia will contact all affected customers by mail to present their vehicle to their preferred Mazda Dealer for the replacement of the ignition switch at no charge.