



MAZDA RECALLS

View your vehicles details below

Model: MAZDA2 E 4 SPEED AUTO 5HB 1.5 NEO

VIN: JM0DE10Y180108359

Year: 2007



YOUR VEHICLE IS AFFECTED BY 1 RECALL

1 Active Recall | 0 Pending Recalls

Result returned on: 05/05/2025 01:28 PM AEST

SEAT LIFTER LINK RECALL

STATUS	RECALL CODE	PRA NUMBER
Active	R201810	2017/15935 REC-000879

Risk

On the drivers seat of the affected vehicles, it is possible that the Seat Height Adjustment Lifter Link may crack, or the Lifter Link Retaining Nuts may separate. In the worst case, the Lifter Link may break or separate from the seat frame, causing the seat to move out of position.

Remedy

Mazda Australia will contact all affected owners. Owners will be advised to present their vehicle to their preferred Mazda Dealer for inspection and repair at no charge.

TAKATA - PASSENGER AIR BAG RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED	RECALL CODE	PRA NUMBER
22/08/2017	R201604	2016/11521

Summary

In the affected vehicles, continued exposure of the passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag

Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

Remedy

Mazda Australia will contact affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the passenger side airbag inflator at no charge.
