



# MAZDA RECALLS

View your vehicles details below

Model: MAZDA2 E 5 SPEED MANUAL 5HB 1.5 NEO

VIN: JM0DE10Y180110504

Year: 2008



## NO OUTSTANDING RECALLS

0 Active Recalls | 0 Pending Recalls

Result returned on: 13/12/2025 02:30 pm AEST

### TAKATA - PASSENGER AIR BAG RECALL

✓ COMPLETED

#### STATUS

Vehicle Repaired

#### DATE COMPLETED

24/07/2017

#### RECALL CODE

R201604

#### PRA NUMBER

2016/11521

#### Summary

In the affected vehicles, continued exposure of the passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag

#### Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

#### Remedy

Mazda Australia will contact affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the passenger side airbag inflator at no charge.

### SEAT LIFTER LINK RECALL

✓ COMPLETED

#### STATUS

Vehicle Repaired

#### DATE COMPLETED

30/07/2020

#### RECALL CODE

R201810

#### PRA NUMBER

2017/15935 REC-000879

**Risk**

On the drivers seat of the affected vehicles, it is possible that the Seat Height Adjustment Lifter Link may crack, or the Lifter Link Retaining Nuts may separate. In the worst case, the Lifter Link may break or separate from the seat frame, causing the seat to move out of position.

**Remedy**

Mazda Australia will contact all affected owners. Owners will be advised to present their vehicle to their preferred Mazda Dealer for inspection and repair at no charge.

---