



# MAZDA RECALLS

View your vehicles details below

Model: MAZDA2 E 5 SPEED MANUAL 5HB 1. 5 MAXX SAFETY

VIN: JM0DE10Y180116199

Year: 2008



## YOUR VEHICLE IS AFFECTED BY 1 RECALL

1 Active Recall | 0 Pending Recalls

Result returned on: 09/05/2025 02:29 PM AEST

### SEAT LIFTER LINK RECALL

| STATUS | RECALL CODE | PRA NUMBER            |
|--------|-------------|-----------------------|
| Active | R201810     | 2017/15935 REC-000879 |

#### Risk

On the drivers seat of the affected vehicles, it is possible that the Seat Height Adjustment Lifter Link may crack, or the Lifter Link Retaining Nuts may separate. In the worst case, the Lifter Link may break or separate from the seat frame, causing the seat to move out of position.

#### Remedy

Mazda Australia will contact all affected owners. Owners will be advised to present their vehicle to their preferred Mazda Dealer for inspection and repair at no charge.

### TAKATA - PASSENGER AIR BAG RECALL

✓ COMPLETED

#### STATUS

Vehicle Repaired

| DATE COMPLETED | RECALL CODE | PRA NUMBER |
|----------------|-------------|------------|
| 28/08/2017     | R201604     | 2016/11521 |

#### Summary

In the affected vehicles, continued exposure of the passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag

#### Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

**Remedy**

Mazda Australia will contact affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the passenger side airbag inflator at no charge.

---