



# MAZDA RECALLS

View your vehicles details below

**Model:** MAZDA6 B AUTOMATIC 4 SPEED LIMITED SEDAN

**VIN:** JM0GG103100167722

**Year:** 2005



## NO OUTSTANDING RECALLS

0 Active Recalls

0 Pending Recalls

**Result returned on:** 09/05/2025 02:30 PM AEST

### TAKATA - DRIVER AIR BAG RECALL

✓ COMPLETED

#### STATUS

Vehicle Repaired

#### DATE COMPLETED

04/12/2017

#### RECALL CODE

R201602

#### PRA NUMBER

2015/14761

#### Summary

In the affected vehicles continued exposure of the driver-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

#### Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

#### Remedy

Mazda Australia will contact all affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the driver-side airbag inflator at no charge.

### TAKATA - PASSENGER AIR BAG RECALL

✓ COMPLETED

#### STATUS

Vehicle Repaired

**DATE COMPLETED**  
04/12/2017

**RECALL CODE**  
R201604

**PRA NUMBER**  
2015/14761

**Summary**

In the affected vehicles, continued exposure of the passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag

**Risk**

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

**Remedy**

Mazda Australia will contact affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the passenger side airbag inflator at no charge.

---