



MAZDA RECALLS

View your vehicles details below

Model: MAZDA6 C HATCH 6 SPEED MANUAL LUXURY SPORTS

VIN: JM0GG103200505710

Year: 2005



NO OUTSTANDING RECALLS

0 Active Recalls

0 Pending Recalls

Result returned on: 07/06/2025 09:00 PM AEST

TAKATA - DRIVER AND PASSENGER AIR BAG RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED

20/07/2017

RECALL CODE

R201601

PRA NUMBER

2015/14761

Summary

In the affected vehicles continued exposure of the driver-side and passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

Remedy

Mazda Australia will contact all affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the driver-side and passenger side airbag inflator at no charge.