



MAZDA RECALLS

View your vehicles details below

Model: B30A DUAL CAB PICK-UP DX 4X2 ABS A/C

VIN: MM0UNY0E300668003

Year: 2007



NO OUTSTANDING RECALLS

0 Active Recalls

0 Pending Recalls

Result returned on: 10/05/2025 12:58 PM AEST

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED

29/11/2013

RECALL CODE

R201001

TAKATA - DRIVER AIR BAG RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED

05/08/2017

RECALL CODE

R201602

PRA NUMBER

2015/14761

Summary

In the affected vehicles continued exposure of the driver-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

Remedy

Mazda Australia will contact all affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the driver-side airbag inflator at no charge.

TAKATA - PASSENGER AIR BAG RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED

05/08/2017

RECALL CODE

R201703

PRA NUMBER

2015/14761 REC-003802

Summary

In the affected vehicles, continued exposure of the passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

Remedy

Mazda Australia will contact affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the passenger-side airbag inflator at no charge.
