



# MAZDA RECALLS

View your vehicles details below

**Model:** CX7A 6 SPEED AUTOMATIC LUXURY

**VIN:** JM0ER103100101639

**Year:** 2006



## NO OUTSTANDING RECALLS

0 Active Recalls

0 Pending Recalls

**Result returned on:** 08/07/2025 03:45 PM AEST

## TAKATA - PASSENGER AIR BAG RECALL

✓ COMPLETED

### STATUS

Vehicle Repaired

### DATE COMPLETED

07/10/2017

### RECALL CODE

R201706

### PRA NUMBER

2017/16232

### Summary

In the affected vehicles, continued exposure of the passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

### Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

### Remedy

Mazda Australia will contact affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the passenger side airbag inflator at no charge.