



# MAZDA RECALLS

View your vehicles details below

Model: MAZDA6 E MANUAL 6 SPEED WAGON DIESEL VIN: JM0GY10R200304654 Year: 2007



## NO OUTSTANDING RECALLS

0 Active Recalls | 0 Pending Recalls

Result returned on: 04/04/2026 04:40 pm AEST

## TAKATA - DRIVER AND PASSENGER AIR BAG RECALL

✓ COMPLETED

STATUS

Vehicle Repaired

DATE COMPLETED

20/12/2017

RECALL CODE

R201601

PRA NUMBER

2015/14761

### Summary

In the affected vehicles continued exposure of the driver-side and passenger-side air bag inflator to high levels of absolute humidity may cause the front air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the frontal air bag.

### Risk

If you are involved in a collision, the airbag can go off with too much explosive force causing sharp metal fragments to shoot out and kill or seriously injure people in the vehicle.

### Remedy

Mazda Australia will contact all affected customers to present their vehicle to their preferred Mazda Dealer for the replacement of the driver-side and passenger side airbag inflator at no charge.

---